



20-60 Chattin Ditcher in Operation

<https://collections.galtmuseum.com/en/permalink/descriptions20393>

Date Range: 1945

Description Level: Item

Material Type: Photograph

Accession No.: 19871008060

Physical Description: 7x 11.6 cm. Black and white photograph

Scope and Content: View of a Chattin No. 20-60 Ditcher cleaning out a lateral irrigation canal near Ontario, Oregon (?).